

From: "Fox, Mary" <FoxML@cdmsmith.com>  
To: "Sheldrake, Sean" <sheldrake.sean@epa.gov>  
"Zhen, Davis" <Zhen.Davis@epa.gov>  
CC: "Scott Coffey" <coffeyse@cdmsmith.com>  
younghs@cdmsmith.com  
Date: 8/10/2018 1:17:02 PM  
Subject: S010

---

Removing sediment from 3rd segment of S010. Liner torn near catcher when driven and doubled in on itself for several feet. No liner for sediment in last several feet of core.

